

Utility Model Patent  
CN 87210843 U

Publication Date: July 6, 1988  
Application Date: July 27, 1987  
Application No.: 87.2.10843  
Applicant: WANG, Shi-Qiang  
                  Huaibei City, Anhui Province, PRC

## BEST AVAILABLE COPY

Title: Negative-Ion Generator Capable of Eliminating Ozone

Abstract:

A negative ion-generator capable of eliminating ozone, being fit for use in hospitals, hotels and homes, with both medical effect and air purifying function. The resolution to the harmful ozone accompanying the emission of negative ion can be achieved by only adding a UV ray emitting device to the existing negative ion generator. As a result, the medical effect of the ion-generator will be greatly enhanced, and it also brings about the effect of trapping and killing mosquitoes and bugs.

Claims:

1. A negative ion-generator capable of eliminating ozone comprising: at least a discharge plate and generating circuit, the feature therein being a UV ray emitting device.
2. A negative ion-generator capable of eliminating ozone of Claim 1, featuring the said UV ray device, the emitting wave length thereof being between  
     $2080 \times 10^{-10}$  (m) and  $3130 \times 10^{-10}$  (m).
3. A negative-ion generator capable of eliminating ozone of Claims 1 and 2, wherein the feature being that said UV ray emitting device locating nearby said discharge comprising negative electrodes (4) and positive electrodes (5).

(19) 中华人民共和国专利局



## (12) 实用新型专利申请说明书

(11) CN 87 2 10843 U

(43)公告日 1988年7月6日

(21)申请号 87 2 10843  
 (22)申请日 87.7.27  
 (23)申请人 王世强  
 地址 安徽省淮北市相山特需公司科研处特  
 (24)设计人 王世强

(74)专利代理机构 煤炭部专利服务中心  
 代理人 张志刚


(51)Int.Cl.<sup>4</sup>

H01T 23/00  
 A61L 9/22  
 F24F 3/16

CN 87 2 10843 U

(54)实用新型名称: 可消除臭氧的空气负离子发生器  
 (55)摘要:

一种能够消除臭氧的空气负离子发生器。适用于医院、宾馆、家庭等各种场所,对人体有医疗作用,并可净化空气。它只将现有的空气负离子发生器上装一可放射紫外线的装置,即解决了产生负离子的同时伴有对人体有害的臭氧问题,更大程度地提高了空气负离子发生器医疗之功效,还可有消毒蚊虫的作用。



882U07718 / 43-332

(BJ)第1452号

说 明 书 附 图





图1



1图2




図3

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.